



Check artery forcep serrated jaws are not damaged or burred

Serrated jaw



Ensure instrument shanks are straight and aligned



Check ratchet (or rack) mesh correctly



Check box joint area for cracks or corrosion



Lock ratchet/rack and drop onto a soft surface from 30cm to prevent jumping off of the rack

