

Caring for your Clamps



The jaw serrations should not contain any burrs and should perfectly mesh




Check box joints for damage and cracking

Check inside box joints for corrosion and cleanliness




Check ratchet (or rack) mesh correctly – check with manufacturer if unsure of the correct ‘set’ of the device



Most have atraumatic jaws and are used in delicate operations

Atraumatic jaw



Ensure shanks are straight and aligned



These clamps are prone to staining or rusting so be extra vigilant