

Caring for your Light Lead



Hold up to light to
see the fibres glow -
damage will be visible



Check that coating of lead is intact



Use light lead
testing machines



Check the ends are correct
- the instrument end should
screw into the scope



Ensure the length
matches tray list