




These scissors must be sharpened carefully as overheating can cause inserts to crack



The two gold bows indicate the presence of Tungsten carbide - this is brazed into the jaw ensuring scissors are more durable and harder



Check that there is no cracking around this brazing and visually spot the faint line of the tungsten carbide along the scissor jaw